

Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error Definition	Errs
1	BRS	L1	0 (captured adj pad) w/ th mask	US-PAT; US-PFGU; B; EPO; JPO; DERENT; TDB	2002/02/08 12:00			0
2	BRS	L2	22 captured adj pad	US-PAT; US-PFGU; B; EPO; JPO; DERENT; TDB	2002/02/08 12:01			0
3	BRS	L3	108 L22" and mask	US-PAT; US-PFGU; B; EPO; JPO; DERENT; TDB	2002/02/08 12:00			0
4	BRS	L4	2 L2 and mask	US-PAT; US-PFGU; B; EPO; JPO; DERENT; IBM	2002/02/08 12:00			0
5	BRS	L5	22 captured adj pad	US-PAT; US-PFGU; B; EPO; JPO; DERENT; IBM	2002/02/08 12:03			0
6	BRS	L6	426 pad near mask	US-PAT; US-PFGU; B; EPO; JPO; DERENT; TDB	2002/02/08 11:33			0
7	BRS	L7	140 16 and (chip or solder)	US-PAT; US-PFGU; B; EPO; JPO; DERENT; TDB	2002/02/08 12:19			0
8	BRS	L8	4643 pad with mask	US-PAT; US-PFGU; B; EPO; JPO; DERENT; TDB	2002/02/08 12:33			0

Type	L #	Hits	Search Text	DBS	Time Stamp	Comments	Error Definition	Error
9	BRS	119	631 (and with mask) same (solder or below)	US- PGPU ; IBM ; EPO; DEMENT	2002/02/08 12:34			0
10	BRS	1110	119 not 115	US- PGPU ; IBM ; EPO; DEMENT	2002/02/08 13:35			0
11	BRS	1111	438/612..cc1s.	US- PGPU ; IBM ; EPO; DEMENT	2002/02/08 13:35			0
12	BRS	112	446	111 and mask	US- PGPU ; IBM ; EPO; DEMENT	2002/02/08 13:49		0
13	BRS	113	212	438/613..cc1s. and mask	US- PGPU ; IBM ; EPO; DEMENT	2002/02/08 13:52		0
14	BRS	114	142	113 not 112	US- PGPU ; IBM ; EPO; DEMENT	2002/02/08 13:50		0
15	BRS	115	97	438/611..cc1s. and mask	US- PGPU ; IBM ; EPO; DEMENT	2002/02/08 13:54		0
16	BRS	116	105	438/98..cc1s. and mask	US- PGPU ; IBM ; EPO; DEMENT	2002/02/08 13:55		0

Type	L #	Bits	Search Text	DBS	Time Stamp	Comments	Error Definition	Error Res
17	BRS	L17	20	JL6 and pad	US-PGDU B1_EPO: JPO: DEMENT / IBM	2002/02/08 13:36		0
18	BRS	L18	694	ellips with mask	US-PGDU B1_EPO: JPO: DEMENT / IBM	2002/02/08 14:06		0
19	BRS	L19	67	ellips near mask	US-PGDU B1_EPO: JPO: DEMENT / IBM	2002/02/08 13:37		0
20	BRS	L20	38	L18 and pad	US-PGDU B1_EPO: JPO: DEMENT / IBM	2002/02/08 14:30		0
21	BRS	L21	650	((ellips or shape) near open\$) same mask	US-PGDU B1_EPO: JPO: DEMENT / IBM	2002/02/08 14:09	Truncation Overflow. Return string from Server is: 5 0 0 Ell	1
22	BRS	L22	13	L18 and solder	US-PGDU B1_EPO: JPO: DEMENT / IBM	2002/02/08 14:30		0



Type	L#	File	Search Text	DBS	Time Stamp	Comments	Error Definition	Err rs
9	BRS	L9	257/779.cc1s. and mask	US-PU: US-PPU: B; EPO; JPO; DEWERM TDB	2002/02/08 16:22			0
10	BRS	LL0	257/678.cc1s. and mask	US-PU: US-PPU: B; EPO; JPO; DEWERM TDB	2002/02/08 16:24			0
11	BRS	L11	114/263.cc1s. and mask	US-PU: US-PPU: B; EPO; JPO; DEWERM TDB	2002/02/08 16:27			0
12	BRS	LL2	24/864.cc1s. and mask	US-PU: US-PPU: B; EPO; JPO; DEWERM TDB	2002/02/08 16:27			0
13	BRS	LL3	24/853.cc1s. and mask	US-PU: US-PPU: B; EPO; JPO; DEWERM TDB	2002/02/08 16:27			0